



TQ3403 Wireless Access Point Version 11.0.5-1.1 Software Release Notes

Read this document before using the management software. The document has the following sections:

- “Supported Platform,” next
- “New Features” on page 1
- “Resolved Issues” on page 2
- “Known issues” on page 2
- “Limitations” on page 4
- “Limitations on Performance” on page 4
- “Supported Countries” on page 4
- “Contacting Allied Telesis” on page 6

Supported Platform

The following access points support version 11.0.5-1.1:

- TQ3403
- TQm3403

The firmware filename is:

- AT-TQ3403-11.0.5-1.1.img
- AT-TQm3403-11.0.5-0.1.img

For instructions on how to upgrade the firmware on the TQ3403 access point, see the TQ3403 *Access Point Installation Guide* at www.alliedtelesis.com/library.

New Features

Here are the new features for the TQ3403 access point version 11.0.5-1.1:

- Support for configuring the Key Holder List. The Key Holder List, used with 802.11r (Fast Roaming), can now be configured manually from the following page:
Settings > VAP/Security > Fast Roaming
- Pre-authentication is now supported on VAPs 1-15 (previously this was only available on VAP0).
When security mode is **WPA-Enterprise** or **OSEN**, pre-authentication on VAPs 0-15 can

be enabled or disabled on the following page, for each VAP:

Settings > VAP/Security > Security

- Support for disabling IEEE802.11b Legacy Rates "1, 2, 5.5, 11" on the Radio settings page.
- Support for allowing the selection of Multicast Rates in addition to IEEE802.11b.

Resolved Issues

Here are the resolved issues for the TQ3403 access point version 11.0.5-1.1:

- QR Code information would not be displayed if the "View QR code" button was clicked repeatedly.
- An AP would sometimes unexpected reboot when Airtime Fairness was enabled.
- When WPA3 Enterprise CCMP mode was set, the message "STASHED CHANGES: NEED TO APPLY STASHED SETTINGS." would be displayed incorrectly.
- When external page redirect was set to an FQDN (not an IP address), after applying settings and rebooting, the web authentication screen would not appear for VAP0 for up to 5 minutes.
- After a wireless client logged in on the Captive Portal page, the welcome screen on the device would not display correctly.
- Wireless connection to specific VAPs would sometimes fail after the AP was startup or when applying settings.
- When a blank setting is saved on Captive Portal's Walled Garden, the "stash change" message would be incorrectly displayed.
- Saving Radio settings would occasionally fail.
- When changing the mode in Radio settings, the popup dialog would sometimes contain incorrect information.
- Whilst managed by an AWC Plug-in, if an AP requested a tech support file that happened to be large, memory usage would spike and communication would sometimes be lost.
- Fixed an issue where the link speed could downgrade from 2.5G to 1000M, then from 1000M to 100M, when repeatedly linked up and then immediately linked down.
- With SNMP enabled, the AP would sometimes not send authentication failure traps when an incorrect community name was used.
- After a Wi-Fi Schedule Profile was assigned to a radio, further configuration on that radio would result in an incorrect error message appearing and GUI functionality would be affected.
- When sending a request to a switch with LLDP, the AP would request an incorrect power consumption value.

Known issues

Here are the known issues for the TQ3403 access points version 11.0.5-1.1

- The Radar Detecting Channel List is cleared when a radio setting is changed.

- ❑ The LAN port takes approximately 30 seconds to start communications after it links up.
- ❑ The LAN port on the access point that is powered from the AC adapter takes approximately one minute to link up when the Ethernet cable is disconnected and connected.
- ❑ On the Legacy Rates on the Advanced Settings page for Radios, you must deselect rates lower than the selected minimum basic rate.
 - The basic rate for Radio 1 can be 1, 2, 5.5, or 11.
 - The basic rate for Radio 2 can be 6, 12, or 24.
- ❑ On the Neighbor AP page in Monitoring, the security is displayed as WEP even when the security is set to OSEN. OSEN is a security option and can be selected when Passpoint is enabled.
- ❑ Communications via IPv6 fail on VAPs with Dynamic VLAN enabled when IP auto-configuration of IPv6 Router Advertisement is enabled.
- ❑ Even when only the primary RADIUS server is specified, a following log might be issued: "RADIUS No response from Authentication server IP ADDRESS:PORT - failover."
- ❑ If a wireless client in the power saving mode does not respond to the access point, it disconnects the wireless client even before the inactivity timer expires.
- ❑ When Vista Manager EX applies a configuration to the access point, the LAN port on the access point goes down for three seconds.
- ❑ Packet losses or communication delay may occur for approximately ten seconds when Neighbor AP Detection is enabled. Leave Neighbor AP Detection disabled if you need to avoid the communication interruption.
- ❑ When the access point is configured as a part of the Wireless Distribution System (WDS), enabling both MAC Access Control and Fast Roaming (IEEE802.11r) on the access point is not supported.
- ❑ The access point with Management VLAN Tag enabled and VLAN ID set to 1 continues to communicate for several minutes even after the VLAN setting of the port on the switch connected to the access point is changed from Tagged 1 to Untagged 1.
- ❑ Single-byte spaces can be entered in the URL field for Captive Portal.
- ❑ The walled garden wildcard entry is case sensitive.
- ❑ When IEEE802.11k is enabled, for some access points with Hidden SSID enabled, information is not shared correctly.
- ❑ A wireless client's RX rate is shown as rounded down on Vista Manager EX.
- ❑ If an IP address is assigned from a DHCP server with a DHCP lease time of 1 minute or less, the AMF guest node feature will not work.
- ❑ A beacon will be transmitted with maximum power even when the transmission output power on Radio 1 is set to "Medium".
- ❑ IEEE802.11r fast roaming is not supported with the following:
 - WPA Enterprise > Dynamic VLAN
 - AMF Application Proxy
- ❑ With Management Frame Protection (MFP) enabled on a VAP, if a duplicate AUTH packet is received, negotiation between the MFP and client will fail. The client will be disconnected, however sometimes a disconnection log will not be output.

Limitations

Here are the limitations for version 11.0.5-1.1:

- ❑ Wireless Distribution System (WDS) and MU-MIMO / OFDMA cannot be enabled at the same time.
- ❑ When Dynamic VLAN is enabled, SNMP cannot get the value of OID 1.3.6.1.2.1.17.4.3.1.1 (MAC address information).
- ❑ Fast Roaming with Enabling Over the DS on Radio 3 (6GHz) is not supported.

Limitations on Performance

Here are the performance limitations for version 11.0.5-1.1:

- ❑ Communication sessions between the AP and wireless clients are registered in a high-speed communication table. However, if the table exceeds the maximum of 4096 entries, communication will then be performed by the CPU resulting in a drop in performance.

The sessions will then be registered using the following information:

- Source IP address
- Source port number
- Destination IP address
- Destination port number
- Transport protocol (UDP/TCP)

When the table maximum is exceeded, the following log will be output:

kernel notice:ECM connection count exceeds 4096.

When this occurs, it is recommended to either:

- reduce the number of wireless clients connected; or
- place the APs closer together.

Supported Countries

The TQ3403 access point continues to support the following countries:

- ❑ Australia
- ❑ Austria
- ❑ Belgium
- ❑ Bulgaria
- ❑ Croatia
- ❑ Cyprus
- ❑ Czech Republic
- ❑ Denmark
- ❑ Estonia

- Finland
- France
- Germany
- Greece
- Hungary
- Ireland
- Italy
- Japan
- Latvia
- Lithuania
- Luxembourg
- Malta
- Netherlands
- New Zealand
- Poland
- Portugal
- Romania
- Singapore
- Slovakia Republic
- Slovenia
- Spain
- Sweden
- Taiwan
- United Kingdom
- United States

Contacting Allied Telesis

If you need assistance with this product, visit the Allied Telesis website at www.alliedtelesis.com/services.

Copyright © 2026 Allied Telesis Inc., Inc.

All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesis Inc., Inc. Allied Telesis Inc. and the Allied Telesis Inc. logo are trademarks of Allied Telesis Inc., Incorporated. All other product names, company names, logos or other designations mentioned herein are trademarks or registered trademarks of their respective owners. Allied Telesis Inc., Inc. reserves the right to make changes in specifications and other information contained in this document without prior written notice. The information provided herein is subject to change without notice. In no event shall Allied Telesis Inc., Inc. be liable for any incidental, special, indirect, or consequential damages whatsoever, including but not limited to lost profits, arising out of or related to this manual or the information contained herein, even if Allied Telesis Inc., Inc. has been advised of, known, or should have known, the possibility of such damages.