



TQ6702e GEN2 Wireless Access Points Version 9.0.4-1.1 Software Release Notes

Read this document before using the management software. The document has the following sections:

- “Supported Platforms,” next
- “New Features” on page 1
- “Enhancements” on page 3
- “Specification Changes” on page 3
- “Resolved Issues” on page 4
- “Known Issues” on page 5
- “Limitations” on page 6
- “Supported Countries” on page 7
- “Contacting Allied Telesis” on page 10

Supported Platforms

The following access point supports version 9.0.4-1.1:

- TQ6702e GEN2

The firmware filename for the TQ6702e GEN2 version 9.0.4-1.1 access point is:

- AT-TQ6702eGEN2-9.0.4-1.1.img

For instructions on how to upgrade the firmware on the TQ6702e GEN2 access point, see the TQ6702e GEN2 *Access Point Installation Guide* at www.alliedtelesis.com/library.

New Features

Version 9.0.4-1.1 for the TQ6702e GEN2 wireless access point added support for the following new features:

- Per VAP Airtime Fairness Percentage control.
 - “Manual” has been added to the Airtime Fairness on the Radio page.
 - When setting the Airtime Fairness to Manual, a “Pre-allocated Airtime Percentage” item will appear in the Advanced Settings tab for each VAP.
 - Airtime Fairness “Enabled” has been changed to “Evenly”
- New SNMP MIBs.

Standard MIB

- Support HOST-RESOURCES-MIB
- Support ENTITIY-MIB
- Support ENTITIY-SENSOR-MIB

Private MIB

- IP address of associated wireless client
- NetBIOS name of associated wireless client
- The total number of associated wireless clients

Radio interface information.

- A unique index for each Radio interface
- The radio channel
- The total number of associated wireless clients for each radio

 New Radio mode options:

Radio1:

- IEEE 802.11b/g/n

Radio2:

- IEEE 802.11a/n
- IEEE 802.11a/n/ac

 Changing RTS Threshold value. Multicast to Unicast conversion. AMF Application Proxy.

- AMF Application Proxy can only be set from AT-Vista Manager.

 Client Isolation per VAP. Inter VAP wireless client isolation.

- the Inter VAP wireless client isolation feature allows two VAPs with the same VLAN ID set for the same Radio to block VAP communication.

 AMF Auto-Recovery.

- AMF Auto-Recovery can only be configured via AMF Master controller.

 Wi-Fi Scheduler.

- A user is able to change the status of Radios and VAPs on a schedule.
- Note that the wireless module of the AP will restart when the schedule is running.

 Changing the authentication page language for Captive Portal Click-through. Two-step authentication for MAC Access Control and Captive Portal. This field will only show on the MAC Access Control GUI if Captive Portal is enabled. A new scan method when Neighbor AP Detection is enabled, allowing the scanning method and scan time to be configured. One of the following scan methods can be selected:

- All Channel (Default setting)
- One Channel

'All Channel' scans the entire band. The scan interval is every 5 minutes.

'One Channel' scans one selected channel. When 'One Channel' is selected, the user can configure:

- Scan interval:
- Scan duration:
- data keep time
- New fields on the “Security > WPA Enterprise” and “MAC Access Control > External RADIUS” page:
 - RADIUS Timeout
 - RADIUS Retransmit
 - Retry interval for Primary

Enhancements

- Improved GUI response time of VAP/Security page:
 - Pages will switch immediately when selecting VAP0 to VAP15.
 - A “Stash” button has been added to the VAP/Security page.

When changing settings for multiple VAPs at once, press the Stash button after editing the settings for each VAP, and then press “Save & Apply” at the end.

Specification Changes

- Proxy ARP support for wireless clients with static IP (not using DHCP) has been added. Proxy ARP will now respond with IP information to the following packets:
 - ARP request
 - ARP reply

in addition to:

 - ARP Probe
 - ARP Announcement
 - DHCP ACK
- The syslog buffer size has been increased from 64Kbyte to 4Mbyte.
- Improvements to configuring Passpoint settings via the GUI.
- “Frequency Band(GHz)” has been added to “Monitoring > Neighbor AP” page and “Monitoring > Associated Client” page.
- When a device reconnects to the network, a DHCP request will be sent immediately. It will not wait for DHCP lease time expiry.

Resolved Issues

Here are the resolved issues for the TQ6702e GEN2 access points version 9.0.4-1.1:

- When the access point was initialized with the Reset button, two identical log entries were added to the reboot.log.
- The AP would sometimes delete the login username and password if configuration from Vista Manager EX was applied at the same time as the AP's Web GUI was accessed.
- The access point would sometimes reboot when a configuration was applied by Vista Manager EX.
- When an access point's system time was corrected by the wireless controller's management, the wireless controller's statistics and the number of connected clients were not displayed.
- When changing Radio mode, the following unnecessary text was included in the popup message: "In addition, any VAP currently configured for WPA will have the CCMP (AES) cipher suite enabled."
- Passpoint osu-providers method-list settings were not being applied correctly from Vista Manager mini.
- When Passpoint OSU Status is enabled, OSU SSID and OSU Providers Server URI are now required before the settings can be applied.
- When a large number of wireless clients were connected, and the AP requested the attWiAcClientTable MIB value, the response time would be long, and would sometimes result in a timeout.
- Passpoint settings could be applied even if the following fields were not set:
 - NAI Realm information
 - Operator Friendly Name
 - OSU SSID
 - OSU Providers Service
- When the country code was CA (Canada) and the location was switched between indoor and outdoor, sometimes the Bandwidth or Channel would be blank in the GUI.
- When Radius Accounting was enabled, certain attributes were not added to the Accounting-Request packet.
- Very occasionally, changing the settings in the AP's web GUI would cause the connection to be lost.
- If the security of a detected access point is WPA3-Personal, the Neighbor AP security is not displayed on Vista Manager EX.
- The access point would fail to reboot after a backup configuration was applied.
- The access point did not store the wireless client's transmit traffic counter correctly, and sent RADIUS accounting packets with invalid traffic counter information.
- The access point would sometimes reboot when the AP tried to restore a configuration.
- When Static LAG was enabled, a wireless client would sometimes temporarily fail to communicate after roaming to a new AP.
- One Private MIB reply was sent even when a number of wireless clients were connected.

- ❑ Channel and bandwidth settings would disappear when the location was switched to indoor 80+80 MHz.
- ❑ It was possible to load a country configuration file that did not match the country code stored on the AP.
- ❑ When the location was changed in the GUI, the correct channel list information for that location would sometimes not load.
- ❑ The access point occasionally rebooted when a large number of log files were output.
- ❑ When Management VLAN Tag was enabled, VLAN-related interface information would incorrectly be included in the Interface MIB.
- ❑ When accessing a neighbor AP list with a private MIB, an SNMP process would sometimes restart.
- ❑ The access point would occasionally fail to move channels when a radar was detected on channels that are generally reserved for radar.
- ❑ Beacons that included AC parameters were showing with no value for WMM Information Element.
- ❑ QR Code information would not display if the “View QR code“ button was clicked repeatedly.
- ❑ A wireless client would fail to connect to the access point using PMKSA cache.
- ❑ When Passpoint is enabled and WPA version is set to 'WPA and WPA2', the cipher suite settings would be empty.
- ❑ The maximum number of Realm Names than can be assigned is 10. It was possible to add more than 10 Realm Names and the VAP would then become unavailable.
- ❑ In Passpoint settings, when NAI realm entries is 10 or more, the access point would reboot.
- ❑ After initially connecting using PMKSA cache, if re-authentication occurred by the RADIUS server, the log would show it was re-authenticated using the PMKSA cache.

Known Issues

Here are the known issues for the TQ6702e GEN2 access points version 9.0.4-1.1:

- ❑ The Radar Detecting Channel List is cleared when a radio setting is changed.
- ❑ The LAN port takes approximately 30 seconds to start communications after it links up.
- ❑ On the Legacy Rates on the Advanced Settings page for Radios, you must deselect rates lower than the selected minimum basic rate.
 - The basic rate for Radio 1 can be 1, 2, 5.5, or 11.
 - The basic rate for Radio 2 can be 6, 12, or 24.
- ❑ On the Neighbor AP page in Monitoring, the security shows WEP even when it is OSEN. OSEN is a security option, which can be used when Passpoint is enabled.
- ❑ Even when only the primary RADIUS server is specified, the following log can be issued: “RADIUS No response from Authentication server IP ADDRESS:PORT - failover.”
- ❑ If a wireless client in the power saving mode does not respond to the access point, it disconnects the wireless client even before the inactivity timer expires.

- ❑ When Vista Manager EX applies a configuration to the access point, the LAN port on the access point goes down for three seconds.
- ❑ Vista Manager EX occasionally fails to manage the access point right after the access point boots up.
- ❑ Packet losses or communication delay may occur for approximately ten seconds when Neighbor AP Detection is enabled. Leave Neighbor AP Detection disabled if you need to avoid the communication interruption.
- ❑ When the access point is configured as a part of the Wireless Distribution System (WDS), enabling both MAC Access Control and Fast Roaming (IEEE802.11r) on the access point is not supported.
- ❑ The access point with Management VLAN Tag enabled and VLAN ID set to 1 continues to communicate for several minutes even after the VLAN setting of the port on the switch connected to the access point is changed from Tagged 1 to Untagged 1.
- ❑ Single-byte spaces can be entered into the Captive Portal URL field.
- ❑ When IEEE802.11k is enabled, for some access points with Hidden SSID enabled, information is not shared correctly.
- ❑ Invalid numbers for VLAN ID starting with “0” are allowed to be saved & applied instead of rejected.
- ❑ A wireless client’s RX rate is shown as rounded down on Vista Manager EX.

Limitations

Here are the limitations for the TQ6702e GEN2 access points version 9.0.4-1.1:

- ❑ LAG, LACP and Cascade mode for the LAN2 Port are not supported.
- ❑ The TQ6702e does not support AC Power Supply. It is powered only by PoE 802.3bt (Class 5).
- ❑ Changing value of the RTS threshold is not supported.
- ❑ Wireless Distribution System (WDS) and MU-MIMO / OFDMA cannot be enabled at the same time.
- ❑ Autonomous Wave Control-Channel Blanket (AWC-CB) is not supported.
- ❑ AWC-Smart Connect (AWC-SC) is not supported.
- ❑ When Dynamic VLAN is enabled, SNMP cannot get the value of OID 1.3.6.1.2.1.17.4.3.1.1 (MAC address information).
- ❑ AWC-Dynamic Client Navigation (AWC-DCN) is not supported.
- ❑ Autonomous Management Framework (AMF) Application Proxy Redirect URL is not supported.

Supported Countries

The TQ6702e GEN2 access point version 9.0.4-1.1 management software supports the following countries:

- Argentina
- Australia
- Austria
- Bangladesh
- Belgium
- Bolivia
- Bosnia and Herzegovina
- Brazil
- Brunei
- Bulgaria
- Cambodia
- Canada
- Chile
- China
- Colombia
- Costa Rica
- Croatia
- Cyprus
- Czech Republic
- Denmark
- Ecuador
- Egypt
- El Salvador
- Estonia
- Finland
- France
- Germany
- Gibraltar
- Greece
- Guatemala
- Honduras
- Hong Kong
- Hungary Iceland
- India

- Indonesia
- Ireland
- Israel
- Italy
- Japan
- Korea
- Kuwait
- Latvia
- Liechtenstein
- Lithuania
- Luxembourg
- Macao
- Macedonia
- Malaysia
- Malta
- Mexico
- Monaco
- Montenegro
- Morocco
- Nepal
- Netherlands
- New Zealand
- Norway
- Pakistan
- Panama
- Paraguay
- Peru
- Philippines
- Poland
- Portugal
- Qatar
- Romania
- Russia
- Saudi Arabia
- Serbia
- Singapore
- Slovakia Republic
- Slovenia

- Spain
- Sweden
- Switzerland
- Taiwan
- Thailand
- Turkey
- Ukraine
- United Arab Emirates
- United Kingdom
- United States
- Uruguay
- Uzbekistan
- Venezuela
- Vietnam

Contacting Allied Telesis

If you need assistance with this product, visit the Allied Telesis website at www.alliedtelesis.com/services.

Copyright © 2024 Allied Telesis Inc., Inc.

All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesis Inc., Inc. Allied Telesis Inc. and the Allied Telesis Inc. logo are trademarks of Allied Telesis Inc., Incorporated. All other product names, company names, logos or other designations mentioned herein are trademarks or registered trademarks of their respective owners. Allied Telesis Inc., Inc. reserves the right to make changes in specifications and other information contained in this document without prior written notice. The information provided herein is subject to change without notice. In no event shall Allied Telesis Inc., Inc. be liable for any incidental, special, indirect, or consequential damages whatsoever, including but not limited to lost profits, arising out of or related to this manual or the information contained herein, even if Allied Telesis Inc., Inc. has been advised of, known, or should have known, the possibility of such damages.